

**Failure to Submit a Disinfectant Level Quarterly Operating Report (DLQOR)  
MONITORING, ROUTINE (DBP), MAJOR/CHLORINE**

The BOLD SPRINGS WSC water system PWS ID 1550017 has violated the monitoring/reporting requirements set by Texas Commission on Environmental Quality (TCEQ) in Title 30, Texas Administrative Code (30 TAC), Section 290, Subchapter F. Public water systems are required to properly disinfect water before distribution, maintain acceptable disinfection residuals within the distribution system, monitor the disinfectant residual at various locations throughout the distribution system, and report the results of that monitoring to the TCEQ on a quarterly basis.

Results of regular monitoring are an indicator of whether or not your drinking water is safe from microbial contamination.

This violation occurred in the monitoring periods: July 1, 2023 – September 30, 2023

We are taking the following actions to address this issue:

To note on the calendar the dates when DLQOR reports are due and double-check to be sure they are accurate.

Please share this information with all people who drink this water, especially those who may not have received this notice directly (i.e., people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

If you have questions regarding this matter, you may contact: Buster Russell, System Operator at 254-479-0750

**Please see letter below.**

Posted on: 1/31/2024

Bold Springs WSC Residents,

We are addressing a violation with TCEQ on submitting our Disinfectant Level Quarterly Operating Report later than the 10 days required to do so at the end of each quarter.

We apologize to all our customers for the inconvenience.

During this quarter we took 124 chlorine residuals from the system and 124 residuals from the well site at Bold Springs WSC. We also had 9 microbial samples that were all good and free from coliform bacteria and E coli. during this time period, July 1<sup>st</sup> –September 30<sup>th</sup>. This report was sent to TCEQ but was after the 10<sup>th</sup> of the October, which is required.

We regret and again apologize that we were past due on submitting the testing results to TCEQ and will stay on top of the situation to make sure this does not happen again.

Please call or email with any questions you might have.

(254)479-0750 [busterrussellconstruction@yahoo.com](mailto:busterrussellconstruction@yahoo.com)

Buster Russell

Bold Springs WSC , Water Operator